HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER WA-79-F

KACHESS DAM, INLET CHANNEL Kachess River, 1.5 miles north of Interstate 90 Easton vicinity Kittitas County Washington

Harvey S. Rice, Photographer, July 1996 (HAER WA-79-F-1 through 3, and HAER WA-79-F -5 through 9)

J. Thomas Wilson, Photographer, September-October 1992 (HAER WA-79-F-4)

INDEX TO BLACK AND WHITE PHOTOGRAPHS

WA-79-F-1	MOUTH OF OPEN SEGMENT, INLET CHANNEL FROM KACHESS LAKE, LOOKING SOUTHWEST (Dam out of sight, approximately 1/4 mile south)
WA-79-F-2	MOUTH OF OPEN SEGMENT, INLET CHANNEL, LOOKING NORTHWEST FROM LEFT SIDE
WA-79-F-3	OPEN SEGMENT OF INLET CHANNEL, KACHESS RESERVOIR TO REAR, FROM BERM OVER START OF BURIED CONDUIT SEGMENT OF INLET CHANNEL (6/96), LOOKING NORTHEAST
WA-79-F-4	OPEN SEGMENT OF INLET CHANNEL, TRASHRACK OVER MOUTH OF BURIED CONDUIT SECTION, GAUGE, LOOKING NORTH, KACHESS RESERVOIR IN BACKGROUND (Low water, 9/92)
WA-79-F-5	INLET CHANNEL, CUT FOR BURIED CONDUIT SECTION, LOOKING SOUTHWEST
WA-79-F-6	OPEN SECTION OF INLET CHANNEL, FROM BURIED CONDUIT TO BASE OF GATE TOWER, LOOKING NORTH

KACHESS DAM, INLET CHANNEL HAER WA-79-F INDEX TO PHOTOGRAPHS (Page 2)

WA-79-F-7 INLET CHANNEL, EGRESS OF BURIED CONDUIT
SEGMENT TO PEN CHANNEL NEAR GATE TOWER,

LOOKING WEST FORM LEFT BANK OF INLET CHANNEL. KACHESS RIVER CHANNEL (1910) TO REAR BEYOND

INLET CHANNEL

WA-79-F-8 INLET CHANNEL, HAND LAID RIPRAP, LOOKING EAST

WA-79-F-9 INLET CHANNEL, RIPRAP DETAIL, LOOKING EAST

WA-79-F-10 Photographic copy of photograph, photographer unknown, July 1911 (original print located at U.S. Bureau of Reclamation Upper

Columbia Area Office, Yakima, Washington). "ORANGE-PEEL

EXCAVATOR DREDGING OUTLET CHANNEL"

WA-79-F-11 Photographic copy of photograph, photographer unknown, 4 April

1911 (original print located at U.S. Bureau of Reclamation Upper

Columbia Area Office, Yakima, Washington). "LOOKING SOUTH FROM INTAKE OF CONDUIT. LIDGERWOOD EXCAVATOR WORKING ON TRENCH EXCAVATION.

TEMPORARY TOWER ON RIGHT"

WA-79-F-12 Photographic copy of photograph, photographer unknown, 27

April 1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office, Yakima, Washington). "GENERAL VIEW OF INTAKE OF CONDUIT AND LOWER END OF LAKE KACHESS, ALSO WHERE DREDGING WILL BE

DONE"

WA-79-F-13 Photographic copy of photograph, photographer unknown, 29 May

1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office, Yakima, Washington). TEAM WORK ON OUTLET TRENCH NEAR STA. 24 AND LIDGERWOOD EXCAVATOR ON TRENCH NEAR STA. 17. SLUICING WASTE BANK RIGHT OF MACHINE AND GRAVEL PLANT

SHOWS ON LEFT. TAKEN FROM DAM SITE NEAR STA. 7,

LOOKING NORTH"

KACHESS DAM, INLET CHANNEL

HAER WA-79-F

INDEX TO PHOTOGRAPHS

(Page 3)

WA-79-F-14	Photographic copy of photograph, photographer unknown, I July
	1911 (original print located at U.S. Bureau of Reclamation Upper

Columbia Area Office, Yakima, Washington). "LIDGERWOOS-

CRAWFORD EXCAVATOR AT WORK ON OUTLET

TRENCH STA. 22-00 SHOWING DUMP ON THE RIGHT, AND

OLD RIVER CHANNEL ON THE LEFT IN THE

FOREGROUND. PICTURE TAKEN NEAR STA. 24-00

LOOKING NORTH"

....

WA-79-F-15 Photographic copy of photograph, photographer unknown, 1 July

1911 (original print located at U.S. Bureau of Reclamation Upper

Columbia Area Office, Yakima, Washington). "OUTLET

TRENCH. PICTURE TAKEN LOOKING NORTH FROM NEAR

STA. 22-00, SHOWING SAND AND GRAVEL BINS IN

FOREGROUND"

WA-79-F-16 Photographic copy of photograph, photographer unknown, 29 July

1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office, Yakima, Washington). "NEW SAND AND

GRAVEL BIN AND CONCRETE MIXING PLANT"

WA-79-F-17 Photographic copy of photograph, photographer unknown, 29 July

1911 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office, Yakima, Washington). "NEW CONCRETE

MIXING PLANT"

WA-79-F-18 Photographic copy of photograph, photographer unknown,

September 1912 (original print located at U.S. Bureau of

Reclamation Upper Columbia Area Office, Yakima, Washington).

"BLASTING IN LAKE (DREDGE) HT. 500'."

WA-79-F-19 Photographic copy of photograph, photographer unknown,

November 1910 (original print located at U.S. Bureau of

Reclamation Upper Columbia Area Office, Yakima, Washington).

"KACHESS DAM - LAKE OUTLET WORKS"

WA-79-F-20 Photocopy of construction drawing, U.S. Reclamation Service,

circa 1995 (original print located at U.S. Bureau of Reclamation

Upper Columbia Area Office, Yakima, Washington). "EXISTING

FEATURES"

KACHESS DAM, INLET CHANNEL

HAER WA-79-F

INDEX TO PHOTOGRAPHS

(Page 4)

WA-79-F-21

Photocopy of construction drawing, U.S. Reclamation Service, September 1995 (original print located at U.S. Bureau of Reclamation Upper Columbia Area Office, Yakima, Washington). "OUTLET WORKS MODIFICATIONS"